ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0361	Chikka Muniswammappa Lyt, 1st Crs	Rama Temple
Segment No.	**Total Length (m)**	
7/S-W0361/S122009	361.58	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	361.58	77.599744	13.065977	77.600409	13.069180	Amruthahalli road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains of main road of Hoodi Muneshwara layout in Ward No 07, Byatarayanapura	2500000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1. Construction of RCC Drain.2.Providing and laying covering slabs.	007-18-000078
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/147/18-19	20/10/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
04/12/2018	03/12/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N.Lokanathreddy		0.00
Phone No.	**E-Mail ID**	
7892875889		

Field Inspection Details

Number of Trees

0

Any Other Information

Name

Pushpalatha.N.d

Date of Inspection

04/12/2018

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

AE(IT)